



00325635

DRADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 121 - 5533		LEASE NAME: West Fork Unit 2	
LOCATION: NENW 19-35-35W		OPERATOR: H+R	
DATE: 9 20 96		INSPECTOR: EBB	
Insp. Type: CA	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol. <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	None	
Pits (Reserve/Production) (Rule 902, 903, 904)	pit at battery site	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	Cement pump base, risers ✓	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)	G+G Gower, took w/c casing difficultly with mud on casing - sign.	
Surface Rehabilitation (Rule 317)	grassland - remove compaction on location and road, reseed ✓	
Miscellaneous	Andy S.	

CORRECTIVE ACTION REQUIRED: Restore + reseed site before winter if possible.
Date Corrective Action Required By: 3-20-96 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site