

Final Reclamation and Stormwater Inspection

Date: 03/15/2023

Operator: CARRIZO NIOBRARA LLC - 10439

Location ID: 431901

Inspection Document #: 708200051

Weld County, CO

Lot 2 Section 18 T7N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Slick Rock 2-18-7-60 Pad

Location ID: 431901



Photo 1. Facing north from the proposed location. Location has not been built with no evidence of oil and gas activities having occurred.

Inspection Photos

Location Name: Slick Rock 2-18-7-60 Pad

Location ID: 431901



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos

Location Name: Slick Rock 2-18-7-60 Pad

Location ID: 431901



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos

Location Name: Slick Rock 2-18-7-60 Pad

Location ID: 431901



Photo 4. Facing west; see comments in Photo 1.

Inspection Photos

Location Name: Slick Rock 2-18-7-60 Pad

Location ID: 431901



Photo 5. Facing east; reference area pictured. Predominantly buffalo grass, sand dropseed, and blue grama.