

# Inspection Photos

March 14, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334821

Location Name: COUEY-67S92W/8NWSE

Inspection Document #: 702801372

Garfield County, CO

NWSE Section 8 T7S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: COUEY-67S92W/8NWSE  
Location ID: 334821



**Photo 1.** Photo taken from the entrance shows an overview of the location.



Inspection Photos  
Location Name: COUEY-67S92W/8NWSE  
Location ID: 334821



**Photo 2.** Photos show production areas.





## Inspection Photos

Location Name: COUEY-67S92W/8NWSE

Location ID: 334821



**Photo 3.** Photo shows a drain line without a bull plug installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801372

Inspection Photos  
Location Name: COUEY-67S92W/8NWSE  
Location ID: 334821



**Photo 4.** Photos show interim areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801372