

Interim and Stormwater Inspection

March 13, 2023

Operator: Providence Operating LLC #10694

Location ID: 448269

Inspection Document #:709400067

Adams County

NWSE, Section 3, 1S67W

Reed Wold

Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Mar 13, 2023 at 12:36:08 PM
9901-9999 E 162nd Pl
Brighton CO 80602
United States



Photo 1. Photo taken of location sign at entrance of location.

Inspection Photos

Location Name: Shook Well pad 3-1-67

Location ID: 448269




Photo 2. Photo taken of unused wattles and weed debris accumulated on site.



Photo 3. Photo taken of unused straw wattles on site.



Inspection Photos

Location Name: Shook Well pad 3-1-67

Location ID: 448269



Photo 4. Photo taken of unused piping on site



Photo 5. See photo 4 comments.

Inspection Photos

Location Name: Shook Well pad 3-1-67

Location ID: 448269



Photo 6. Photo taken of weed debris in the corners of the perimeter fence.



Photo 7. Photo of outside the perimeter fence, trash and weed debris accumulated in the landscaping.



Inspection Photos

Location Name: Shook Well pad 3-1-67

Location ID: 448269



Photo 8. Photo of trash blown onto site's landscaping.



Photo 9. Photo of downed silt fence at entrance of location.