



Inspection Photos  
Location Name: UPRR 24 PAN AM C#1  
Location ID: 319922




Photo#1 Production Tank

Photo#2 Separator/Gas Meter/Automation RTU

Inspection Photos  
Location Name: UPRR 24 PAN AM C#1  
Location ID: 319922



Photo#3 Wellhead



Photo#4 **Fitting Leaking Gas**

Inspection Photos  
Location Name: UPRR 24 PAN AM C#1  
Location ID: 319922



Photo#5 Showing Production for 3/17/2023

Photo#6 Showing Production for 3/16/2023

Inspection Photos  
Location Name: UPRR 24 PAN AM C#1  
Location ID: 319922



Photo#7 Showing Production for 3/17/2023

Photo#8 Showing Production for 3/16/2023

Inspection Photos  
Location Name: UPRR 24 PAN AM C#1  
Location ID: 319922



**Photo#9 Showing Production for the month of March**