

Interim Reclamation and Stormwater Inspection

March 16, 2023

Operator: EDGE ENERGY II LLC- #10671

Location ID: 443574

Inspection Document #: 697504576

Weld County, CO

NWNE Section 16 T10N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Thomas 16-C Pad
Location ID: 443574



Photo 1. Aerial imagery from 2021 illustrates the Operator has performed interim reclamation to reduce the disturbance area only needed for production operations.



Inspection Photos
Location Name: Thomas 16-C Pad
Location ID: 443574



Photo 2. Photo taken along the southern interim reclamation area, facing East. Photo illustrates mowing operations have been conducted and the location appears to be managed. Undesirable vegetation (tumbleweeds) was observed within interim reclamation areas with perennial vegetation.



Photo 3. Photo taken along the southern interim reclamation area, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Thomas 16-C Pad
Location ID: 443574



Photo 4. Photo taken along the southern interim reclamation area, facing West. See comments under Photo 2.

Note- introduced grass species (e.g., crested wheatgrass) were planted which are not reflective of reference areas.



Photo 5. Photo taken along the northwestern well pad area, facing North. Photo illustrates unused equipment being stored on location.

Inspection Photos
Location Name: Thomas 16-C Pad
Location ID: 443574



Photo 6. Photo taken along the northern interim reclamation area, facing West. See comments under Photo 2.



Photo 7. Photo taken along the northern interim reclamation area, facing East. See comments under Photo 2.

Inspection Photos
Location Name: Thomas 16-C Pad
Location ID: 443574



Photo 8. Reference photo taken from the northern location, facing East. Photo illustrates native, shortgrass prairie vegetation mostly consisting of Blue grama and Buffalo grass.

