

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802



Pic 1 wellhead



Pic 2 unused tank on location needs to be removed

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802

Mar 15, 2023 at 1:05:32 PM
40.016724,-104.888110
Veld County
COGCC



Pic 3 tank on location needs to be removed

Mar 15, 2023 at 1:07:20 PM
40.016866,-104.888614
Veld County
COGCC



Pic 4 Tanks

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802



Pic 5 tanks, stained soil near loadout line.



Pic 6 Motor house

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802

Mar 15, 2023 at 1:10:47 PM
40.017119, -104.888840
Veld County
COGCC



Pic 7 Motor house, trash and unused equipment needs to be removed from motor house. Stained soil needs to be removed

Mar 15, 2023 at 1:11:10 PM
40.017119, -104.888840
Veld County
COGCC



Pic 8 stained soil in motor house needs to be removed

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802

Mar 15, 2023 at 1:11:22 PM
40.017119,-104.888840
Veld County
COGCC



Pic 9 ECD, Separator

Mar 15, 2023 at 1:11:40 PM
40.017119,-104.888840
Veld County
COGCC



Pic 10 ECD flame.

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802




Pic 11 GMR, Separator



Pic 12 transfer motor, stained soil needs to be removed.

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802



Pic 13, Gas meter run shows production time of previous day

Pic 14 trash inside gas meter run needs to be removed

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802



Pic 15 stained soil by gas meter run needs to be removed



Pic 16 flow manifold, stained soil needs to be removed

Inspection Photos
Location Name: David Howard B-1
Location ID: 317802



Pic 17 transfer pump, trash and stained soil needs to be removed.