

Inspection Photos

API: 071-09074

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/20/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023

Inspection Photos



Photo 1. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023

Inspection Photos



Photo 2. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023

Inspection Photos



Photo 3. Facing toward the pit. Pit was permitted with liner however there is no liner in the pit. No freeboard marker.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023

Inspection Photos



Photo 4. Facing toward the southeast side of the location. There is grey colored dirt piled up with remnants of pit liner debris. It appears the pit was excavated and material and liner was left in this area. The berm around the pit material is degraded and has not contained the material.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023

Inspection Photos



Photo 5. There is oil in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09074 | Date: 3/20/2023