

**Inspection Photos**  
**Location: McCartney Engineering / Seedorf #1**  
**Facility ID: 252056**



**Photo 1 – Tank battery location**



**Photo 2 – Subsidence around former tank battery location**



**Inspection Photos**  
**Location: McCartney Engineering / Seedorf #1**  
**Facility ID: 252056**



**Photo 3 – Subsidence around former tank battery**




**Photo 4 –**



**Inspection Photos**  
**Location: McCartney Engineering / Seedorf #1**  
**Facility ID: 252056**



**Photo 5 – Staining around former wellhead location**



**Photo 6 – Staining around former wellhead location**



**Inspection Photos**  
**Location: McCartney Engineering / Seedorf #1**  
**Facility ID: 252056**



**Photo 7 – Unused equipment left on site**