

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785




Photo 1 – Wellhead



Photo 2 – Stained Soil at Wellhead

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Colorado Oil and Gas Conservation Commission
40.72907, -104.08896, 4920.5ft, 122°
03/16/2023 14:41:04

Photo 3 – Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.72979, -104.08854, 4936.1ft, 311°
03/16/2023 14:42:15

Photo 4 – Separators and ECD

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Rohn LB22-62HN
Location ID: 430785




Photo 7 – Tank – Content and Capacity