

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #9285 From entrance to location.



Photo #9295 From entrance to location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



**Photo #9286 Multiple loadlines open ended.**



**Photo #9287 Multiple loadlines open ended.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #9288 Multiple loadlines open ended.



Photo #9360 Calibration cards not conspicuously posted.