

Inspection Photos

API: 071-06204

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/27/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06204 | Date: 3/27/2023

Inspection Photos



Photo 1. There is erosion along the access road at this drainage crossing
Lat/Long:37.05023,-104.66580. This embankment needs to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06204 | Date: 3/27/2023

Inspection Photos



Photo 2. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06204 | Date: 3/27/2023