

Inspection Photos
Location Name: Yoxall Farms
Spill ID: 477437



Photo 1 – Spill point. Surface scraping to expose pipelines, no remedial excavation

Inspection Photos
Location Name: Yoxall Farms
Spill ID: 477437



Photo 2 – Corroded pipes and staining at base of surface scraping.



Photo 3 – Staining at header

Inspection Photos
Location Name: Yoxall Farms
Spill ID: 477437



Photo 4 – Site overview as seen from banks of Big Dry Creek