

Final Reclamation and Stormwater Inspection

Date: 03/23/2023

Operator: P O & G OPERATING LLC - 10634

Location ID: 324936

Inspection Document #: 708200073

Kit Carson County, CO

NENW Section 14 T11S R46W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photos 1 & 2. Facing south along the access road. Photos illustrate that the access road has not been reclaimed with evidence of road base.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 3. Facing north from the location. Unknown pvc pipe and posts remain on location and will need to be removed.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 4. Facing southwest near the PA well. Photo illustrates non-uniform vegetation cover resulting in bare soil. Possible compaction or contaminated soil issues.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 5. Facing northwest near the PA well. Photo illustrates undesirable vegetation (e.g. kochia) and debris observed on location.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 6. See comments in Photo 5.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 7. Facing west near the PA well; see comments in Photo 5.

Inspection Photos
Location Name: PTEX-LOWE-611S46W
Location ID: 324936



Photo 8. Facing east near the former pump jack location. Gravel and road base remain on location.



Photo 9. Google Earth aerial imagery illustrating the access road that will need to be reclaimed (highlighted in red) for this well/location. The other access roads will be addressed under a separate inspection.