

**TEP Rocky Mountain LLC
Unocal GM 11-34
Location #335408**



View from entrance to location



Open cellar around GM 224-34 wellhead

**TEP Rocky Mountain LLC
Unocal GM 11-34
Location #335408**



Sediment migration around wellheads

Sediment migration across location

**TEP Rocky Mountain LLC
Unocal GM 11-34
Location #335408**



Sediment migration. Lack of maintenance.

Erosion. Sediment migration crosses location

**TEP Rocky Mountain LLC
Unocal GM 11-34
Location #335408**



Erosion and sediment migration from tank battery and upper well pad.




View from tank battery. Erosion. Sediment migration across location.

TEP Rocky Mountain LLC Unocal GM 11-34 Location #335408



Sign at tank battery



Gas meter calibration card not conspicuously posted.