



99999999

**OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**☐ NOTICE OF UNSATISFACTORY INSPECTION☒ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

API No. 05	121 - 07608	LEASE NAME:	Haas B #1-B
LOCATION:	SWNE 15-35-55	OPERATOR:	Consolidated O & G
DATE:	3-18-97	INSPECTOR:	EBB
Insp. Type: HR	Insp. Status: DA	PA: (N) N	Pass/Fail: P F Viol.: Y (N) NOV: Y N

**INSPECTION ITEM****COMMENTS****INPUT**

<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	Cultivated	
<b>Miscellaneous</b>		



00400517

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.