

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location ID: 334570



Photo #9387 From entrance to location.



Photo #9388 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location ID: 334570



Photo #9397 Calibration cards not conspicuously posted.



Photo #9400 Capacity reduced due to Stormwater in tank containment



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34NESW

Location ID: 334570



Photo #9405 Loadline open ended.