

Inspection Photos
Location Name: Marie Gerhardt B6
Location ID: 318331



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Marie Gerhardt B6
Location ID: 318331



Photo 3 Unused Pump jack parts and dead tumble weeds all around location.

Photo 4 Unused Pump jack parts and dead tumble weeds all around location.

Inspection Photos
Location Name: Marie Gerhardt B6
Location ID: 318331



Photo 5 Unused Pump jack parts and dead tumble weeds all around location.

Photo 6 Unused Pump jack parts and dead tumble weeds all around location.

Inspection Photos
Location Name: Marie Gerhardt B6
Location ID: 318331



Photo 7 Unused Ag panel and dead tumble weeds all around location.

Photo 8 Unused Pump jack parts and dead tumble weeds all around location.

Inspection Photos
Location Name: Marie Gerhardt B6
Location ID: 318331



Photo 9 Unused Electric panel and meter box.

Photo 10 Location.