

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



View looking South from entrance to well pad

View looking North towards well pad entrance

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



Production pad view from well pad



Entrance view of production pad

TEP Rocky Mountain LLC
GM 323-28
Location #335318



Disconnected and unused equipment



No gas meter calibration card posted for verification

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



No gas meter calibration card posted for verification



Unstable slope and sediment migration

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



Unstable slope and sediment migration



Sign at tank battery

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



Open end tank valve



Standing water due to drainage full of sediment

**TEP Rocky Mountain LLC
GM 323-28
Location #335318**



Lower lease road from production pad



Lease road exit on to paved county road