

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 223-22 Pad

Location ID: 324058



Photo # 3583 From entrance to location



Photo # 3584 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 223-22 Pad

Location ID: 324058



Photo # 3585 Location



Photo # 3586 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 223-22 Pad

Location ID: 324058



Photo # 3587 Location



Photo # 3592 Meter calibration info not conspicuously posted





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 223-22 Pad

Location ID: 324058



Photo # 3598 Debris



Photo # 3599 Debris