

Inspection Photos

March 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335291

Location Name: SAVAGE-66S94W/28SWNW

Inspection Document #: 702801392

Garfield County, CO

SWNW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/28SWNW
Location ID: 335291



3/23/23
-107.899032
342° N



Photo 1. Photos show production areas



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801392

Inspection Photos
Location Name: SAVAGE-66S94W/28SWNW
Location ID: 335291



Photo 2. Photos show storage of unused hose equipment in the tank battery.



Inspection Photos
Location Name: SAVAGE-66S94W/28SWNW
Location ID: 335291



Photo 3. Photo shows a wildlife protection BMP in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801392

Inspection Photos
Location Name: SAVAGE-66S94W/28SWNW
Location ID: 335291



Photo 4. Photos show two (2) unmarked anchors at the east of the location.

Inspection Photos
Location Name: SAVAGE-66S94W/28SWNW
Location ID: 335291



Photo 5. Photos show interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801392