

Inspection Photos

March 23, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335282

Location Name: SAVAGE-66S94W/28SWSW

Inspection Document #: 702801398

Garfield County, CO

SWSW Section 28 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-66S94W/28SWSW
Location ID: 335282



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: SAVAGE-66S94W/28SWSW
Location ID: 335282



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801398

Inspection Photos

Location Name: SAVAGE-66S94W/28SWSW

Location ID: 335282




Photo 3. Photos taken from the north of the location show degradation at a stormwater drain inlet/sediment trap (left) and outlet (right).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801398

Inspection Photos

Location Name: SAVAGE-66S94W/28SWSW

Location ID: 335282



Photo 4. Photos show offsite degradation (erosion, sediment deposition) resulting from concentrated flows discharged from a stormwater drain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801398

Inspection Photos
Location Name: SAVAGE-66S94W/28SWSW
Location ID: 335282



Photo 5. Photo shows interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801398