

## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088



**Photo 1 – Maintenance Tank**




**Photo 2 – Separators**

**Inspection Photos**  
**Location Name: Little State LD 11-74HN Tank Battery**  
**Location ID: 438088**



**Photo 3 – Gas Meters**




**Photo 4 – Compressor**



**Inspection Photos**  
**Location Name: Little State LD 11-74HN Tank Battery**  
**Location ID: 438088**




**Photo 5 – Compressor**



**Photo 6 – Unmarked Riser**



**Inspection Photos**  
**Location Name: Little State LD 11-74HN Tank Battery**  
**Location ID: 438088**



**Photo 7 – Unmarked Riser**



**Photo 8 – Unmarked Riser**



## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088



**Photo 9 – Unmarked Riser – Tag Faded**



**Photo 10 – Unused Pipes and Fittings**



## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088




**Photo 11 – Separators**



**Photo 12 – Unmarked Riser**



**Inspection Photos**  
**Location Name: Little State LD 11-74HN Tank Battery**  
**Location ID: 438088**



**Photo 13 – Unmarked Risers**



**Photo 14 – Unmarked Risers**

## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088



**Photo 15 – Produced Water Tanks**



**Photo 16 – ECDs and VRU**



## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088



**Photo 17 – VRTs and Oil Tanks**



**Photo 18 – LACT**


## Inspection Photos

Location Name: Little State LD 11-74HN Tank Battery

Location ID: 438088



**Photo 19 – Instrumental Air Unit**



**Photo 20 – Unmarked Risers**



**Inspection Photos**  
**Location Name: Little State LD 11-74HN Tank Battery**  
**Location ID: 438088**



**Photo 21 – Tank Battery Signs at Entrance**