

LARAMIE ENERGY LLC, NVega/1D Pad

Location # 334451



Location – Photo #01737

Wellheads – Photo #01738

LARAMIE ENERGY LLC, NVega/1D Pad

Location # 334451



Separators – Photo #01739



Tank Battery – Photo #01741

LARAMIE ENERGY LLC, NVega/1D Pad

Location # 334451



Gas Meter – Photo #01740



Cut Slope Erosion/Run-On to Location – Photo #01750

LARAMIE ENERGY LLC, NVega/1D Pad

Location # 334451



Cut Slope Erosion/Run-On to Location – Photo #01748



Degradation/Transport of Sediment – Photo #01751

LARAMIE ENERGY LLC, NVega/1D Pad

Location # 334451



**Lease Road Degradation/Transport of Sediment –
Photo #01754**

**Lease Road Degradation/Transport of Sediment –
Photo #01756**