



ADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 121 - 05496

LEASE NAME: WFL #9

LOCATION: NW SW 19-35-55

OPERATOR: H+R

DATE: 9-30-96

INSPECTOR: EBBinkley

Insp. Type: ☒ A

Insp. Status: PA

PA: Y

☒ N

Pass/Fail: P

☒ F

Viol.: Y

☒ N

NOV: Y

☒ N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs

(Rule 210, 604.c(4))

H+R pumped cement

✓

Pits (Reserve/Production)

(Rule 902, 903, 904, 905)

yet to be pumped

Fences

(Rule 603.b.7, 604.C.(3), 1002.A)

in MILLET FIELD,

Tank Battery Equipment

(Rule 603.b.3, 604)

Fire Walls/Berms/Dikes

(Rule 603.b.12, 604)

General Housekeeping

(Rule 603)

Spills (Oil/Water)

(Rule 907)

Bradenhead

(Rule 207.b)

Drilling Well/Workover

(Rule 317)

H+R

Surface Rehabilitation

(Rule 1002, 1003, 1004, 1103)

incomplete

Miscellaneous

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By: 3-30-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.