

CAERUS PICEANCE LLC, 697-21A-66S97W/21SENE

Location # 335476



Wellheads – Photo #01818



Separators/Snow Removal – Photo #01821

CAERUS PICEANCE LLC, 697-21A-66S97W/21SENE

Location # 335476



Tank Battery – Photo #01819



Chemical Tank – Photo #01820

CAERUS PICEANCE LLC, 697-21A-66S97W/21SENE

Location # 335476



Methanol Tank – Photo #01823



**Lease Road Degradation/Transport of Sediment –
Photo #01825**

CAERUS PICEANCE LLC, 697-21A-66S97W/21SENE

Location # 335476



**Lease Road Degradation/Transport of Sediment –
Photo #01828**



**Lease Road Degradation/Transport of Sediment –
Photo #01829**