

# Inspection Photos

API: 043-06204

Operator: JAVERNICK OIL

Inspection Date: 3/31/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06204 | Date: 3/31/2023

## Inspection Photos



**Photo 1.** Facing south along the access road. A new cattle guard has been installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06204 | Date: 3/31/2023

## Inspection Photos



**Photo 2.** Facing toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06204 | Date: 3/31/2023

## Inspection Photos



**Photo 3.** The pro-panel installed for secondary containment has a large gap in the bottom. Secondary containment should have been installed per 603.o. for any significant modifications.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06204 | Date: 3/31/2023

## Inspection Photos



**Photo 4.** Facing toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06204 | Date: 3/31/2023