

Reclamation and Stormwater Inspection

Date: 03/31/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 460414

Inspection Document #: 708200084

Weld County, CO

NENE Section 7 T9N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 1. Oily waste appears to have been cleanup up from tank and gravel near the bottom.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414




Photo 2. Facing east within the eastern interim area, illustrating debris on location.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414




Photo 3 . Facing northeast; see comments in Photo 2.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 4. Facing east near the eastern boundary line. Photo illustrates debris that has left location and will need to be disposed of.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 5. Facing southwest near sediment trap; see comments in Photo 2.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 6. See comments in Photo 2.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 7. Facing east near the northern portion of the production area. Heavy rutting was observed during this inspection and is being documented for operator awareness at this time.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 8. Facing south; see comments in Photo 7.

Inspection Photos
Location Name: LD07-01 Multi
Location ID: 460414



Photo 9. Facing east; see comments in Photo 7.