

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2023

Submitted Date:

03/29/2023

Document Number:

708300236

FIELD INSPECTION FORM

| Loc ID 452797 | Inspector Name: Morris, Matthew | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 32 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|------------------------------------|---|-------------------|--|--------------|-----------------|-------------|-------------|------------|---------|---------------------------------------|-------------|-----------------|------|----------------------------|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|--------|------|----|------------|----|-----------|-----------------|----|
| Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1700 LINCOLN ST STE 3950 City: DENVER State: CO Zip: 80203 | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>, LARAMIE</td> <td></td> <td>cogccnotifications@laramie-energy.com</td> <td></td> </tr> <tr> <td>Kellerby, Shaun</td> <td></td> <td>shaun.kellerby@state.co.us</td> <td></td> </tr> </tbody> </table> | | | | | Contact Name | Phone | Email | Comment | , LARAMIE | | cogccnotifications@laramie-energy.com | | Kellerby, Shaun | | shaun.kellerby@state.co.us | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Contact Name | Phone | Email | Comment | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| , LARAMIE | | cogccnotifications@laramie-energy.com | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>452788</td><td>WELL</td><td>PR</td><td>01/27/2019</td><td>GW</td><td>077-10508</td><td>BCU 0993-21-05E</td><td>PR</td></tr> <tr><td>452789</td><td>WELL</td><td>PR</td><td>02/28/2019</td><td>GW</td><td>077-10509</td><td>BCU 0993-21-01E</td><td>PR</td></tr> <tr><td>452790</td><td>WELL</td><td>PR</td><td>02/15/2019</td><td>GW</td><td>077-10510</td><td>BCU 0993-21-02E</td><td>PR</td></tr> <tr><td>452791</td><td>WELL</td><td>PR</td><td>03/01/2019</td><td>OW</td><td>077-10511</td><td>BCU 0993-21-04W</td><td>PR</td></tr> <tr><td>452792</td><td>WELL</td><td>PR</td><td>02/09/2019</td><td>GW</td><td>077-10512</td><td>BCU 0993-21-05W</td><td>PR</td></tr> <tr><td>452793</td><td>WELL</td><td>PR</td><td>01/02/2019</td><td>GW</td><td>077-10513</td><td>BCU 0993-21-09E</td><td>PR</td></tr> <tr><td>452794</td><td>WELL</td><td>PR</td><td>01/28/2019</td><td>GW</td><td>077-10514</td><td>BCU 0993-21-07E</td><td>PR</td></tr> <tr><td>452795</td><td>WELL</td><td>PR</td><td>03/01/2019</td><td>GW</td><td>077-10515</td><td>BCU 0993-21-01W</td><td>PR</td></tr> <tr><td>452796</td><td>WELL</td><td>PR</td><td>01/02/2019</td><td>GW</td><td>077-10516</td><td>BCU 0993-21-08E</td><td>PR</td></tr> <tr><td>452798</td><td>WELL</td><td>PR</td><td>03/04/2019</td><td>GW</td><td>077-10517</td><td>BCU 0993-21-03W</td><td>PR</td></tr> <tr><td>452799</td><td>WELL</td><td>PR</td><td>03/01/2019</td><td>GW</td><td>077-10518</td><td>BCU 0993-21-04E</td><td>PR</td></tr> <tr><td>452800</td><td>WELL</td><td>PR</td><td>01/28/2019</td><td>GW</td><td>077-10519</td><td>BCU 0993-21-06E</td><td>SI</td></tr> <tr><td>452801</td><td>WELL</td><td>PR</td><td>01/09/2019</td><td>GW</td><td>077-10520</td><td>BCU 0993-21-09W</td><td>PR</td></tr> <tr><td>452802</td><td>WELL</td><td>PR</td><td>01/07/2019</td><td>GW</td><td>077-10521</td><td>BCU 0993-21-10W</td><td>PR</td></tr> <tr><td>452803</td><td>WELL</td><td>PR</td><td>01/04/2019</td><td>GW</td><td>077-10522</td><td>BCU 0993-21-10E</td><td>PR</td></tr> <tr><td>452804</td><td>WELL</td><td>PR</td><td>03/02/2019</td><td>GW</td><td>077-10523</td><td>BCU 0993-21-02W</td><td>PR</td></tr> <tr><td>452805</td><td>WELL</td><td>PR</td><td>02/03/2019</td><td>GW</td><td>077-10524</td><td>BCU 0993-21-06W</td><td>PR</td></tr> <tr><td>452821</td><td>WELL</td><td>PR</td><td>01/10/2019</td><td>OW</td><td>077-10525</td><td>BCU 0993-21-08W</td><td>PR</td></tr> <tr><td>452831</td><td>WELL</td><td>PR</td><td>02/02/2019</td><td>GW</td><td>077-10526</td><td>BCU 0993-21-07W</td><td>PR</td></tr> </tbody> </table> | | | | | Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | 452788 | WELL | PR | 01/27/2019 | GW | 077-10508 | BCU 0993-21-05E | PR | 452789 | WELL | PR | 02/28/2019 | GW | 077-10509 | BCU 0993-21-01E | PR | 452790 | WELL | PR | 02/15/2019 | GW | 077-10510 | BCU 0993-21-02E | PR | 452791 | WELL | PR | 03/01/2019 | OW | 077-10511 | BCU 0993-21-04W | PR | 452792 | WELL | PR | 02/09/2019 | GW | 077-10512 | BCU 0993-21-05W | PR | 452793 | WELL | PR | 01/02/2019 | GW | 077-10513 | BCU 0993-21-09E | PR | 452794 | WELL | PR | 01/28/2019 | GW | 077-10514 | BCU 0993-21-07E | PR | 452795 | WELL | PR | 03/01/2019 | GW | 077-10515 | BCU 0993-21-01W | PR | 452796 | WELL | PR | 01/02/2019 | GW | 077-10516 | BCU 0993-21-08E | PR | 452798 | WELL | PR | 03/04/2019 | GW | 077-10517 | BCU 0993-21-03W | PR | 452799 | WELL | PR | 03/01/2019 | GW | 077-10518 | BCU 0993-21-04E | PR | 452800 | WELL | PR | 01/28/2019 | GW | 077-10519 | BCU 0993-21-06E | SI | 452801 | WELL | PR | 01/09/2019 | GW | 077-10520 | BCU 0993-21-09W | PR | 452802 | WELL | PR | 01/07/2019 | GW | 077-10521 | BCU 0993-21-10W | PR | 452803 | WELL | PR | 01/04/2019 | GW | 077-10522 | BCU 0993-21-10E | PR | 452804 | WELL | PR | 03/02/2019 | GW | 077-10523 | BCU 0993-21-02W | PR | 452805 | WELL | PR | 02/03/2019 | GW | 077-10524 | BCU 0993-21-06W | PR | 452821 | WELL | PR | 01/10/2019 | OW | 077-10525 | BCU 0993-21-08W | PR | 452831 | WELL | PR | 02/02/2019 | GW | 077-10526 | BCU 0993-21-07W | PR |
| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452788 | WELL | PR | 01/27/2019 | GW | 077-10508 | BCU 0993-21-05E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452789 | WELL | PR | 02/28/2019 | GW | 077-10509 | BCU 0993-21-01E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452790 | WELL | PR | 02/15/2019 | GW | 077-10510 | BCU 0993-21-02E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452791 | WELL | PR | 03/01/2019 | OW | 077-10511 | BCU 0993-21-04W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452792 | WELL | PR | 02/09/2019 | GW | 077-10512 | BCU 0993-21-05W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452793 | WELL | PR | 01/02/2019 | GW | 077-10513 | BCU 0993-21-09E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452794 | WELL | PR | 01/28/2019 | GW | 077-10514 | BCU 0993-21-07E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452795 | WELL | PR | 03/01/2019 | GW | 077-10515 | BCU 0993-21-01W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452796 | WELL | PR | 01/02/2019 | GW | 077-10516 | BCU 0993-21-08E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452798 | WELL | PR | 03/04/2019 | GW | 077-10517 | BCU 0993-21-03W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452799 | WELL | PR | 03/01/2019 | GW | 077-10518 | BCU 0993-21-04E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452800 | WELL | PR | 01/28/2019 | GW | 077-10519 | BCU 0993-21-06E | SI | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452801 | WELL | PR | 01/09/2019 | GW | 077-10520 | BCU 0993-21-09W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452802 | WELL | PR | 01/07/2019 | GW | 077-10521 | BCU 0993-21-10W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452803 | WELL | PR | 01/04/2019 | GW | 077-10522 | BCU 0993-21-10E | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452804 | WELL | PR | 03/02/2019 | GW | 077-10523 | BCU 0993-21-02W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452805 | WELL | PR | 02/03/2019 | GW | 077-10524 | BCU 0993-21-06W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452821 | WELL | PR | 01/10/2019 | OW | 077-10525 | BCU 0993-21-08W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 452831 | WELL | PR | 02/02/2019 | GW | 077-10526 | BCU 0993-21-07W | PR | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| General Comment: <div style="height: 40px; border: 1px solid black;"></div> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

COGCC Inspection Report Summary

On 3/28/2023 at approximately 15:35, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Gunderson/0993-21-05 Pad at Location ID #452797 in Mesa County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Stormwater; Inadequate chemical tank secondary containment due to snow build-up
- 2) Stormwater; Site degradation from snow plow causing transport of sediment and lack of stabilization

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, Wildlife Management area.

LocationOverall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | |
|--|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: _____ | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Pipe rail fencing | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 6 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 19 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Chemical tanks | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 19 | | |

| | | |
|--|------|-------|
| Comment: All wells on plunger lift | | Date: |
| Corrective Action: | | Date: |
| Type: Emission Control Device | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 19 | |
| Comment: Pressure transducers located on Bradenheads | | |
| Corrective Action: | | Date: |
| Type: Vertical Heated Separator | # 19 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: Centralized containment | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| CONDENSATE | 1 | 400 BBLS | HEATED STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: Centralized containment | | | | |
| Corrective Action: | | | | Date: |

| | | | | | | |
|--------------------|----------|-------------------------|---------------------|-------------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 7 | 400 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | Centralized containment | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 452788 | Type: | WELL | API Number: | 077-10508 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452789 | Type: | WELL | API Number: | 077-10509 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452790 | Type: | WELL | API Number: | 077-10510 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452791 | Type: | WELL | API Number: | 077-10511 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452792 | Type: | WELL | API Number: | 077-10512 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452793 | Type: | WELL | API Number: | 077-10513 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452794 | Type: | WELL | API Number: | 077-10514 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 452795 | Type: | WELL | API Number: | 077-10515 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | |
|--|------------|-----------------------|------------|------------------|
| Facility ID: 452796 | Type: WELL | API Number: 077-10516 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452798 | Type: WELL | API Number: 077-10517 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452799 | Type: WELL | API Number: 077-10518 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452800 | Type: WELL | API Number: 077-10519 | Status: PR | Insp. Status: SI |
| <u>Idle Well</u> | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | |
| Comment: Last produced 1/1/2023 | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452801 | Type: WELL | API Number: 077-10520 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452802 | Type: WELL | API Number: 077-10521 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452803 | Type: WELL | API Number: 077-10522 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: 452804 | Type: WELL | API Number: 077-10523 | Status: PR | Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: Producing | | | | |

| | | | | | | | | | |
|--------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Corrective Action: | | Date: | | | | | | | |
| | | | | | | | | | |
| Facility ID: | 452805 | Type: | WELL | API Number: | 077-10524 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452821 | Type: | WELL | API Number: | 077-10525 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 452831 | Type: | WELL | API Number: | 077-10526 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------------|
| Berms | | | | | | |
| Other | Fail | | | | | Site degradation/sediment transport |
| | | Berms | | | | |
| | | Culverts | | | | |
| | | | | Material Handling And Spill Prevention | Fail | Inadequate secondary containment |
| | | Gravel | | | | |
| | | Ditches | | | | |

Comment: 1) Inadequate chemical tank secondary containment due to snow build-up
 2) Site degradation from snow plow causing transport of sediment and lack of stabilization
 Location lacks stabilization which may lead to future tracking issues
 Unable to inspect all BMPs due to snow cover

Corrective Action: 1) Comply with Rule 1002
 2) Comply with Rule 1002

Date: 04/13/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403360149 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6066199 |
| 708300237 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6066194 |