

Inspection Photos

4/05/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334732

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 1: Photos 1-2 provide an overview of the Location from north, northeast, southeast to south.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 3: Secondary containment at the single 300 bbl produced water/condensate tank is inadequate to contain a spill.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 4: Secondary containment at the three 300 bbl produced water/condensate tanks is inadequate to contain a spill.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 6: Chemical container lacks required marking/labeling/signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 7: Discharge point on the northwest end of the Location- outlet appears armored.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 8: Interim areas.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334732



Photo 9: The storage, placement, or maintenance of equipment, vehicles, trailers, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.