

Inspection Photos

Loc: 333348

Operator: OXY USA INC

Inspection Date: 4/10/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 1. Drone aerial photo facing northeast at the Drill site 3 compressor. There was a leak that has blackened the facility and areas of the ground and sprayed out to the northeast off the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 2. The area northeast off the location has been blackened from the spill that occurred at the compressor facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 3. Facing east at the Drill site 3 compressor. There was a leak that has blackened the facility and areas of the ground that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 4. The is stained soils along the east side of the compressor.



Inspection Photos



Photo 5. Facing southeast at the north side of the Drill site 3 compressor. There is oil stained soils that have sprayed out north of the compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 6. Facing northeast off the location. The vegetation and ground has been blacked from the spill at the compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 7. Facing northeast off the location. The vegetation and ground has been blacked from the spill at the compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023

Inspection Photos



Photo 8. There was some trash/debris found north of the location that needs to be cleaned up. The vegetation in this area is also blackened from the spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333348 | Date: 4/10/2023