

# Inspection Photos

April 5, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324083

Location Name: MACKLEY-67S94W/3NWNW

Inspection Document #: 702801440

Garfield County, CO

NWNW Section 3 T7S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MACKLEY-67S94W/3NWNW  
Location ID: 324083



**Photo 1.** Photo shows production areas.





Inspection Photos  
Location Name: MACKLEY-67S94W/3NWNW  
Location ID: 324083



**Photo 2.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801440



Inspection Photos  
Location Name: MACKLEY-67S94W/3NWNW  
Location ID: 324083



**Photo 3.** Photo shows wildlife protection BMPs are in disrepair.



Inspection Photos  
Location Name: MACKLEY-67S94W/3NWNW  
Location ID: 324083



**Photo 4.** Photos show anchor markers are in disrepair/anchors are unmarked.



Inspection Photos  
Location Name: MACKLEY-67S94W/3NWNW  
Location ID: 324083



**Photo 5.** Photos show examples of the interim area.

