

Inspection Photos

April 10, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 421223

Location Name: McLin A Pad

Inspection Document #: 702801446

Garfield County, CO

SESW Section 12 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



4/10/23
+39.536628,-107.617453
354° N

Photo 1. Photo taken from entrance shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801446

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 2. Photos show interim areas to the west. Species shown include cheatgrass (List C Noxious), purple mustard, Russian thistle and common stork's-bill (annual, undesirable plant species).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801446

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 3. Photo shows interim areas to the north. Note the singular seeded perennial grass (circled).

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 4. Photo shows interim areas to the north. Note the noxious weed Scotch thistle (circled).

Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 5. Photo shows a Russian knapweed skeleton with new growth (circled).



Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 6. Photo shows the eastern interim areas are established with perennial grasses.
Note also Scotch thistle.



Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 7. Photo shows the southern and eastern interim areas directly adjacent to the working pad area are bare.



Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 8. Photo shows rill erosion occurring in western interim areas. Sediment has overtopped a wattle.



Inspection Photos
Location Name: McLin A Pad
Location ID: 421223



Photo 9. Photo shows rill erosion occurring in western interim areas. Note also dominance of bare ground and lack of perennial vegetation.



Inspection Photos
Location Name: McLin A Pad
Location ID: 421223




Photo 10. Photo shows rill erosion occurring in northern interim areas.

