

Inspection Photos
Location Name: Razor 26K PAD
Location ID: 430308



Photo 1 – Unused Pumping Unit at 26-3524H

Photo 2 – Unused Equipment and Stained Soil

Inspection Photos
Location Name: Razor 26K PAD
Location ID: 430308



Photo 3 – Unused Pollution Pot and Kill Switch

Photo 4 – Stained Soil

Inspection Photos
Location Name: Razor 26K PAD
Location ID: 430308



Photo 5 – Wellhead Sign

Photo 6 – North Wellheads

Inspection Photos
Location Name: Razor 26K PAD
Location ID: 430308



Photo 7 – South Wellheads

Photo 8 – Sign at Entrance