

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 1 – Signs at Entrance



Photo 2 – Methanol Tank

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 3 – 2208B – Stained Soil




Photo 4 – 2208B – Stained Soil

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 5 – 2208B Wellhead



Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695




Photo 7 – 2207A Wellhead – Unmarked Riser and Stained Soil



Photo 8 – 2207A Wellhead Sign

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 9 – 2207A Wellhead – Stained Soil



Photo 10 – 2703A Wellhead Sign – Stained Soil and Unused Pipe

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 11 – 2712H Wellhead – Stained Soil



Photo 12 – 2712H Wellhead Sign

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695




Photo 13 – 2712H Wellhead – Stained Soil



Photo 14 – Tank Battery

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 15 – Heater Treaters



Photo 16 – Flare and ECD

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 17 – VRU




Photo 18 – Water Tank Labels

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 19 – LACT



Photo 20 – LACT

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 21 – Tank Labels



Photo 22 – Tank Battery

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 23 – Tank Battery Sign



Photo 24 – Production Equipment

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 25 – Equipment



Photo 26 – Unmarked Risers

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695




Photo 27 – Unmarked Risers



Photo 28 – Unmarked Risers

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 29 – Unmarked Risers



Photo 30 – Heater Treaters

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 29 – Unmarked Risers



Photo 30 – Heater Treaters

Inspection Photos
Location Name: Razor 22D PAD
Location ID: 430695



Photo 31 – Gas Lift Injection Meter Houses