

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Location ID: 324133



Photo #9603 From entrance to location.



Photo #9604 Calibration cards not conspicuously posted.