

Storm water Management and Erosion control

Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Access Road/Assoc. Location #:



Access Road overview: The access road is approximately 20ft from the nearest body of water

Section/Township/Range: 4 7S95W

Storm water Management and Erosion control

Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Access Road/Assoc. Location #: 324133

Network: Apr 7, 2023 at 12:00:32 PM M



Photo #9606 Access road cut slope lacks stabilization.

Network: Apr 7, 2023 at 12:00:46 PM M



Photo #9607 Sediment encroaching on access road.

Storm water Management and Erosion control

Access Road/Assoc. Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4NWNW

Access Road/Assoc. Location #: 324133



Photo #9608 Sediment and rocks encroaching on access road.