


Inspection Photos


Operator: Omimex Petroleum Inc (66190)

Lease: Malander 8--34-6-45

Facility ID/API, 295588 / 05-095-06214



1. Lease sign on meter shed




2. Inside Meter shed, Vertical gas separator, gas scrubber, Meter run.

Inspection Photos


Operator: Omimex Petroleum Inc (66190)

Lease: Malander 8--34-6-45

Facility ID/API, 295588 / 05-095-06214



3. Chart was last changed 12-1-2022



24. Door off of Meter shed



Inspection Photos

Operator: Omimex Petroleum Inc (66190)

Lease: Malander 8--34-6-45

Facility ID/API, 295588 / 05-095-06214



5. Wellhead




6. Gas leak on flowline blowing out of ground by wellhead.

Inspection Photos


Operator: Omimex Petroleum Inc (66190)

Lease: Malander 8--34-6-45

Facility ID/API, 295588 / 05-095-06214



7. Fiberglass water tank without labeling.



8. Fiberglass water tank missing hatch cover.