


# Inspection Photos


Operator: Omimex Petroleum Inc (66190)

Lease: Bledsoe 7-3-5-45

Facility ID/API, 278962 / 05-125-09365




1. Lease sign on meter shed




2. Meter shed

**Inspection Photos**  
**Operator: Omimex Petroleum Inc (66190)**  
**Lease: Bledsoe 7-3-5-45**  
**Facility ID/API, 278962 / 05-125-09365**




**3. Chart was last changed 1/5/2023**




**4. Kimray valve propped open with a plug and 1/2" valve.**

Inspection Photos  
Operator: Omimex Petroleum Inc (66190)  
Lease: Bledsoe 7-3-5-45  
Facility ID/API, 278962 / 05-125-09365




5. Wellhead with plunger lift



6. Gas blowing at 2" T before going into ground, also leaking on same line inside shed.

**Inspection Photos**  
**Operator: Omimex Petroleum Inc (66190)**  
**Lease: Bledsoe 7-3-5-45**  
**Facility ID/API, 278962 / 05-125-09365**




**7. Cement pad for pumping unit**




**8. Location**

Inspection Photos  
Operator: Omimex Petroleum Inc (66190)  
Lease: Bledsoe 7-3-5-45  
Facility ID/API, 278962 / 05-125-09365



9. Cement vault east of well at central battery.



10. Location Central battery east of well.