

Inspection Photos
Location Name: Razor 08E-1704
Location ID: 441730



Photo 1 – Wellhead



Photo 2 – Sign – Does Not Reflect Current Operator

Inspection Photos
Location Name: Razor 08E-1704
Location ID: 441730



Photo 3 – Unused Rods



Photo 4 – Unused Concrete Blocks

Inspection Photos
Location Name: Razor 08E-1704
Location ID: 441730



Photo 5 – Tank Battery



Photo 6 – Sign does not reflect Current Operator

Inspection Photos
Location Name: Razor 08E-1704
Location ID: 441730



Photo 7 – ECD and Flare



Photo 8 – Heater Treater

Inspection Photos
Location Name: Razor 08E-1704
Location ID: 441730



Photo 9 – Gas Meters