

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5306 From entrance to location



Photo # 5307 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5308 Location



Photo # 5309 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5310 Location



Photo # 5311 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5312 Debris




Photo # 5313 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5314 Debris



Photo # 5317 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 220-21 Pad

Location ID: 335334



Photo # 5320 Debris