

# TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

Location # 311561



Wellheads – Photo #02106



Separators – Photo #02107

# TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

## Location # 311561



**Tank Battery – Photo #02108**



**Open-Ended Load Line – Photo #02109**

# TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/29NWNE

Location # 311561



**Check Dam Sediment Build-Up – Photo #02112**

**Inadequate Vehicle Tracking BMP – Photo #02115**