

Inspection Photos

April 10, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 335514

Location Name: JOLLEY-66S91W/21NENW

Inspection Document #: 702801465

Garfield County, CO

NENW Section 21 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 1. Photo taken from the north shows an overview of the location.



Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801465

Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 3. Photo shows aerial imagery of the location. The western portion of the location does not appear to be necessary for production activities and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801465

Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 4. Photo shows the western portion of the location does not appear to be necessary for production activities and has not been reclaimed.



Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 5. Photo shows the western portion of the location does not appear to be necessary for production activities and has not been reclaimed.



Inspection Photos
Location Name: JOLLEY-66S91W/21NENW
Location ID: 335514



Photo 6. Photo shows an example of interim areas to the east.