

Inspection Photos

API: 071-09525

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/13/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09525 | Date: 4/13/2023

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09525 | Date: 4/13/2023

Inspection Photos



Photo 2. There is a dripping leak at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09525 | Date: 4/13/2023

Inspection Photos



Photo 3. Well sign posted at meter run.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09525 | Date: 4/13/2023