

Inspection Photos

API: 071-09590

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/13/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 4/13/2023

Inspection Photos



Photo 1. Facing southwest along the access road toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 4/13/2023

Inspection Photos



Photo 2. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 4/13/2023

Inspection Photos



Photo 3. There is oily fluid in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 4/13/2023

Inspection Photos



Photo 4. There is an erosion channel along the cut slope that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09590 | Date: 4/13/2023