

Inspection Photos
Location Name: Hankins 1
Location ID: 318634



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: Hankins 1
Location ID: 318634



Photo 3 TB sign.



Photo 4 TB tank placards are faded and hard to read.

Inspection Photos
Location Name: Hankins 1
Location ID: 318634



Photo 5 Horizontal Heated Separator.



Photo 6 Gas Meter Run.

Inspection Photos
Location Name: Hankins 1
Location ID: 318634



Photo 7 PW vessel.