

**KT Resources
AHU 30-31
Location # 316146**



Tank battery



Meter house

**KT Resources
AHU 30-31
Location # 316146**



Horizontal separator and meter house



Well head

**KT Resources
AHU 30-31
Location # 316146**



Lack of stabilization/compaction



Lack of stabilization/compaction

**KT Resources
AHU 30-31
Location # 316146**



Lack of sufficient BMP's



Erosion channel from location

**KT Resources
AHU 30-31
Location # 316146**



Access road lack of stabilization



Access road lack of stabilization

**KT Resources
AHU 30-31
Location # 316146**



Dry weeds in tank containment



Dry weeds in tank containment

**KT Resources
AHU 30-31
Location # 316146**



Dry weeds in tank containment next to tank burner



Weeds have turned into debris