

Inspection Photos

4/17/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334431

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334431



Photo 1: Photos 1-2 taken from the south end of the working pad. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show interim reclamation of areas not needed for production has been performed, or is “in process” of being completed.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #334431



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334431



Photo 3: Photos 3-4 taken from the north end of the working pad. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also show interim reclamation of areas not needed for production has been performed, or is “in process” of being completed. BMPs to allow for proper stormwater discharge not observed.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #334431



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #334431



Photo 5: Tank battery facility on the southwest end of the Location. Battery signage not observed.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334431



Photo 6: Photos 6-7 taken from the interim areas of the Location, facing north, east, south and west. Interim reclamation “in process”.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334431



Photo 7: See comments under photo 6