

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 1 – Wellhead – Stained Soil



Photo 2 – Unused Tubing

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 3 – Stained Soil at Exhaust



Photo 4 – Stained Soil

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 7 – Oily Waste at Pumping Unit



Photo 8 – Wellhead – Leaking – Stained Soil – Oil Waste

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 9 – Wellhead – Leaking – Stained Soil – Oil Waste



Photo 10 – Flare and ECD

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 11 – Heater Treater



Photo 12 – Tank Battery

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 13 – Tank Battery Sign