

Inspection Photos

April 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 324011

Location Name: SAVAGE-67S94W/1SESE

Inspection Document #: 702801481

Garfield County, CO

SESE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1SESE
Location ID: 324011



Photo 1. Photos show production areas.



Inspection Photos
Location Name: SAVAGE-67S94W/1SESE
Location ID: 324011



Photo 2. Photos show an example of interim areas to the south (left) and north (right).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801481